

TIG WELDING GLOVES GANTS DE SOUDEUR TIG



These **split deerskin TIG welding gloves** have been reinforced with **Kevlar thread stitching**, making them perfect for protecting you on the most demanding jobs. With their **rigid 5in split cowhide safety paddle**, your forearms will be injury-free, while an additional split deerskin appliqué on the palm will keep you working **safely**.

Ces **gants de soudeur TIG en cuir de chevreuil fendu** ont été renforcé à l'aide de **coutures en fil de kevlar**, les rendant parfait pour vous protéger lors des travaux les plus exigeant. Avec leur **palette de sécurité rigide de 5 po en cuir de vache fendu**, vos avant-bras seront exempt de blessures, tandis qu'un appliqué supplémentaire en peau de chevreuil fendu sur la paume vous permettra de travailler en toute **sécurité**.



- 1** Split deer leather palm and back
Paumes et dos en cuir de chevreuil fendu
- 2** Palm with split deerskin protection
Paumes avec protection en peau de chevreuil fendu
- 3** Rigid 5in cowhide split forearm safety paddle
Palette de sécurité rigide de 5 po en cuir de vache fendu à l'avant-bras
- 4** Aramid thread seams
Coutures en fil d'aramide

PRODUCT # DE PRODUIT

060346

SIZES | GRANDEUR

M-2XL | M-2TG

PACKAGING | EMBALLAGE

UNTAGGED | SANS ÉTIQUETTE

TIG WELDING GLOVES GANTS DE SOUDEUR TIG

CARE INSTRUCTIONS | CONSEILS D'ENTRETIEN

- Gloves can be washed several times. However, remain vigilant in monitoring their condition. Groupe BBH is not responsible for any loss of performance due to washing and premature deterioration that this may cause.
- Surface wash** with slightly dampened and soft cloth or brush.
If the stains remain, you can use a glycerin-based soap.
 - Hang to dry** in a cool, well-ventilated area.
 - Dry completely** before storing to prevent mold growth.
 - Store gloves in a dry place away from sunlight.**
- Do not machine wash.
 - Do not immerse in water.
 - Do not use detergents, bleaches or abrasive soaps.
 - Do not tumble dry or iron.
 - Do not wring.
 - Do not put in contact with chemicals such as acetone or solvent.
- Les gants peuvent être lavés plusieurs fois. Par contre, demeurer vigilant en surveillant leur état. Groupe BBH n'est pas responsable des pertes de performance due aux lavages et à la détérioration prématurée que cela peut causer.
- Laver en surface** avec un chiffon doux ou une brosse souple légèrement humide.
Si les tâches persistent, vous pouvez utiliser un savon à base de glycérine.
 - Suspendre pour sécher** dans un endroit bien aéré et frais.
 - Sécher complètement** avant de les ranger pour éviter la formation de moisissure.
 - Entreposer** les gants dans un endroit sec à l'abri du soleil.
- Ne pas laver à la machine.
 - Ne pas immerger dans l'eau.
 - Ne pas utiliser de détergent, d'agent blanchissant et de savons abrasifs.
 - Ne pas sécher à la machine ou repasser.
 - Ne pas tordre.
 - Ne pas mettre en contact avec des substances chimiques comme l'acétone ou du dissolvant.




PALM CIRCUMFERENCE MEASUREMENT MESURE DE LA CIRCONFÉRENCE DE LA MAIN

Wrap a measuring tape around the widest part of the hand.
Enroulez un ruban à mesurer autour de la partie la plus large de la main.

LENGTH MEASUREMENT MESURE DE LA LONGUEUR

Measure from the top of the middle finger to the wrist crease.
Mesurez à partir du sommet du majeur jusqu'au pli du poignet.



		XS TP	S P	M M	L G	XL TG	2XL 2TG
CIRCUMFERENCE CIRCONFÉRENCE/	MAN (in)	6.49-7.04	7.08-7.63	7.67-8.62	8.66-9.80	9.84-10.98	11.02
	WOMEN (in)	6.29-6.65	6.69-7.04	7.08-7.44	7.48-7.83	7.87-8.22	8.26
	HOMME (mm)	165-179	180-194	195-219	220-249	250-279	280+
	FEMME (mm)	160-169	170-179	180-189	190-199	200-209	210+
LENGTH LONGUEUR	MAN (in)	6.69-7.04	7.08-7.44	7.48-7.83	7.87-8.22	8.26-8.62	8.66
	WOMEN (in)	5.90-6.45	6.49-6.85	6.88-7.24	7.28-7.63	7.67-8.03	8.06
	HOMME (mm)	170-179	180-189	190-199	200-209	210-219	220+
	FEMME (mm)	150-164	165-174	175-184	185-194	195-204	205+